

EUROCONTROL Digital NOTAM Project

Industry Requirements for Digital NOTAM Submission
Washington, 29 August 2007

Presented by:


Eduard Porosnicu
EUROCONTROL



Content

- Why Digital NOTAM
- What is a Digital NOTAM
- Implementation plans in Europe


Aeronautical Information



Digital Aeronautical Data

static

static + dynamic



Digital NOTAM can improve safety



Closed runway example



Work on the runway

The image is a composite illustrating airport operations during runway work. It features several key elements:

- ATIS Tower:** A stylized illustration of a tower with the call sign **WFXM** and lightning bolts, labeled **ATIS** in red.
- TWR Control Room:** An illustration of an air traffic control room with controllers at consoles, labeled **TWR** in red.
- PIB Document:** A document titled **PIB** (Pilot Information Bulletin) with a red circle highlighting a specific section of text.
- Airport Map:** A detailed map of an airport showing runways, taxiways, and various facilities. A red exclamation mark and question mark (**!?!?**) are placed over a runway area marked **Under Construction**. Other map features include:
 - Runway 05L/23R with a displaced threshold at elevation 212.
 - Runway 05R/23L with a displaced threshold at elevation 227.
 - Runway 05C/23C with a displaced threshold at elevation 249.
 - Navigation aids: ILS LLZ (111.55), ILS GP (266), VOR/DME MCT (113.55), and NDB MCH (428).
 - Other facilities: NEA Hangar, Engine Test Area, Light Aircraft Area "ROMPA", MSF Accommodation, Radar, Fire Service Training Ground, and various taxiways (A1-A10, B1-B10, C1-C10, D1-D10, E1-E10, F1-F10, G1-G10, H1-H10, J1-J10, K1-K10, L1-L10, M1-M10, N1-N10, O1-O10, P1-P10, Q1-Q10, R1-R10, S1-S10, T1-T10, U1-U10, V1-V10, W1-W10, X1-X10, Y1-Y10, Z1-Z10).

Work on the runway



56 feet

AIR TRANSPORT

MANCHESTER / SINGAPORE

Emirates 777 in runway near-miss

New Zealand investigators say pilots failed to heed warning that usable length was shortened by repair work

An Emirates Boeing 777 nearly collided with a truck and other equipment at the end of the main runway at Auckland airport, New Zealand on take-off last month. The investigator says the pilots had failed to take note of information that the published usable length had been reduced because the far end of the runway was under maintenance.

New Zealand's Transport Accident Investigation Commission (TAIC) has disclosed that it is investigating the incident, which occurred at about 16:15 on 22 March.

The TAIC says: "The 777...was taking off from the main runway, which had been shortened due to repair works under way at one end," but evidently the crew were not aware of this. "[The pilots] had to increase power to maximum thrust during the take-off when they noticed the machinery working at the end of the runway," says the TAIC.

It adds that "the aircraft cleared the work area by the permitted margin [and] nobody was injured". Equipment in the work area included a truck and a car, TAIC air accident investigator Peter Williams told Flight's online news service *Air Transport Intelligence*.

Williams says that for normal full-length operations on the runway in use, 05R, the declared accelerate-stop distance available is 3,623m (11,900ft), but the distance "from taxiway A10 at the time of the incident was 2,170m". He adds that the runway work at the airport was scheduled to take place between 19 March and 8 April and information about it was included "in the [airport's broadcast] automatic terminal information service, NOTAMS [notices to airmen] and the operator's briefing package".

Maintenance mishaps from the past

On 16 July 2003 a UK-based Excel Airlines Boeing 737-800 with 197 people on board took off over the top of heavy vehicles carrying out scheduled end of runway maintenance at Manchester airport. The crew began the take-off with de-rated power assuming the full length would be available, but lifted off safely by slamming on full power as they topped the mid-runway rise and saw the vehicles. In October 2000 a Singapore Airlines Boeing 747-400 collided disastrously with construction equipment in poor visibility, while attempting take-off from a runway that was closed for maintenance at Taipei, Taiwan, resulting in 83 deaths.

ACCIDENT KIERAN DALY / LONDON

LIGHTING



Developments/Projects that could prevent such events

- On-board moving maps
 - airport layout
 - own ship position
- Graphically displayed taxi route/clearance
- Also needed
 - actual operational status of airport movement area elements
 - requires "digital NOTAM"



What is a “digital NOTAM”

- Example - TWY closure
 - Today, published as NOTAM

A0874/03 NOTAMN

Q) EBBU/QMXLC/IV/M/A/000/999/5054N00429E005

A) EBBR

B) 0308250500 C) 0310271600

<OK for computers>

E) TAXIWAYS OUTER 7 AND E6 CLSD

<not OK for computers>

Digital NOTAM = Fully data modelled NOTAM

- intended for computers
- using the **Aeronautical Information Exchange Model (AIXM)** version 5

What is a “digital NOTAM”

- Instead of

```
<text>TAXIWAYS OUTER 7 AND E6 CLSD</text>
```
- Use explicit feature properties
 - For example...

```
<taxiway>  
  <name>OUTER 7</name>  
  <status>CLOSED</status>  
</taxiway>  
<taxiway>  
  <name>E6</name>  
  <status>CLOSED</status>  
</taxiway>
```
 - This is a much more closer to a truly digital NOTAM
 - ... and the goal of AIXM 5

What digital NOTAM could change

- Improved Pre-flight Information

ABOVE RULES ARE AS SPECIFIED BELOW:

	ARRIVALS	DEPARTURES
MONDAY	0600-2255	0600-2055
TUESDAY	0600-2255	2200-2225
WEDNESDAY	0600-2255	0600-2055
THURSDAY	0600-2255	0600-2055
FRIDAY	0600-2255	0600-2255
SATURDAY	0600-1755	0700-1555
SUNDAY	0600-2255	0800-2255

Current text PIB

AGA : Q) EGTG/QMRXX/IV/NBO/A/000/999/5129N00028W005
FROM 07/02/16 18:38 TO 07/03/31 07:00 A0428/07
E) RWY 09R/27L. DUE W/IF RWY ENTRY/EXIT NB10 CLOSED.

AGA : Q) EGTG/QMRLC/IV/NBO/A/000/999/5129N00028W005
FROM 06/09/05 05:00 TO 07/04/30 05:00 A2243/06
E) DUE W/IF TWY B SOUTH CLSD BTN 'R' AND 'R'.
TWY 'R' CLSD BTN 'A' AND 'B' AND DIVERTED VIA NEW GREEN CL AND BLUE
EDGE LGT. ADS CYN

COM : Q) EGTG/QIWB/I/NBO/A/000/999/5129N00028W005
FROM 06/12/16 08:39 TO 07/12/31 23:59 EST A3175/06
E) MLS RWY 27R U/S, MAY RADIATE ON TEST.

RAC : Q) EGTG/QPACH/I/NBO/A/000/999/5129N00028W005
FROM 06/07/14 08:14 TO PERM A1785/06
E) STAR VIA OCKHAM (NORTH AND WEST): GENERAL INFO NOTE 7 AMEND TO READ
EN-ROUTE HOLDING: DURING PERIODS OF CONGESTION IN THE LONDON TMA, TPC
VIA OCK IF MAY BE REQUIRED TO HOLD AT OKESI (CPT VOR/TIME R268/31.TNM,
INBOUND TRK 106 DEG MAG, TURNING LEFT AT OKESI, OUTBOUND LEG TIME 1
MIN 30 SEC)

RAC : Q) EGTG/QSTXX/IV/NBO/A/000/999/5129N00028W005
FROM 07/02/05 11:00 TO 07/04/20 23:59 EST A0326/07
E) TELEPHONE/FAX NUMBERS CHANGED, NEW NUMBERS -
TEL 020 8745 3326 (NATS LTD)
TEL 020 8745 3163 (NATS LTD FBU)
FAX 020 8745 3491/3492 (NATS LTD FBU)
UK AIP AD 2-EGLL-1-1 2.2 AND AD 2-EGLL-1-21 PARA 8E REFER

NAVV: Q) EGTG/QWCLM/IV/M/A/000/000/5129N00028W001
FROM 07/02/12 08:45 TO 07/03/02 12:15 H0310/07
D) 0845-1215
E) AUS 07-02-0159/A85
CAPTIVE HELIUM BALLOON 5129N 00020W (ISLEWORTH, WEST LONDON).
CONTACT 020 8583 2984.
F) SFC 0380FT AGL

OTH : Q) EGTG/QPATY/I/NBO/A/000/999/5129N00028W005
FROM 06/07/10 10:14 TO 07/07/10 09:00 EST A1734/06
E) TRIAL P-RNAV STAR, AIP SUP S14/04 REFERS

OTH : Q) EGTG/QOBCE/IV/M/A/000/999/5129N00028W005
FROM 06/12/19 14:23 TO 07/12/31 23:59 A3210/06
E) MULTIPLE CRANES IN TERMINAL 5 CONSTRUCTION SITE ADJOINING RWY 09L

PIB -

File Edit View Favorites Tools Help

Address 3-12-04%2022:34&ifr=true&vfr=true&operational=false&features=111111111111 Go

PRE-FLIGHT INFORMATION BULLETIN

FROM: Tue Jun 10 22:34:00 CEST 2003 TO: Thu Dec 04 22:34:00 CET 2003

FLIGHT RULES: **VFR IFR**

PURPOSE: ALL

SELECTED FEATURES: AERODROME/HELIPORT APRON DME PARKING AREA ILS MARKER
NDB RUNWAY TAXIWAY VOR


- AERODROME EHAM
FROM 2003-07-02T13:00:00 TO 2003-10-02T13:00:00
BIRD CONCENTRATION
 - RUNWAY 01L/19R
 - RUNWAY DIRECTION 01L
FROM 2003-06-09T00:25:00 TO 2003-06-09T12:00:00 EST
TRANSMISSIOMETER OUT OF SERVICE
 - TAXIWAY W7
FROM 2003-06-15T23:18:00 TO 2003-06-17T03:00:00
TWY OUT OF SERVICE ACFT HEAVIER THAN 19000 KGS
- NDB CH 521314.22N 0043327.36E



What digital NOTAM could change

- Virtual AIP
 - Dynamic ENR tables for a flight trajectory


(HE) A16			
12:01 ▲ RA SDA 330600N 0305700E	$\frac{171^\circ}{351^\circ}$		Cairo ACC FREQ: 127.700 MHz or 126.6 MHz
	119 KM	FL250 FL055	
12:18 ▲ MILAD 320201N 0310406E	$\frac{172^\circ}{352^\circ}$		AVBL for TFC Landing "AXD" INTL FLT to cross "AXD" FL100 or above
12:24 ▲ BALTIM VOR/DME BLT 313144N 0310721E	56 KM	FL060	
12:45 ▲ CAIRO VOR/DME CVO 300532N 0312318E	$\frac{169^\circ}{349^\circ}$		
	162 KM		
(LC) A411			
	$\frac{124^\circ}{304^\circ}$		LC D03 ACTIVATED
12:51 ▲ MENUJ 294701N 0315206E	58 KM	FL250 FL090	
13:02 ▲ KAMIS 291701N 0323606E	$\frac{125^\circ}{305^\circ}$		FL070 FL050
	90 KM	FL085	




- Support innovative devices

Implementation plans

More about AIXM -> www.aixm.aero



2007-2008: Digital NOTAM Trial



Digital NOTAM Implementation

The European approach

We need global coordination!